Safety Alert

Filing/Polishing at the Lathe

Do not wear gloves, loose fitting clothing or jewelry near rotating shafts or moving machine parts.









Do not wrap abrasive around shaft.

