
COVID-19: Protect Yourself and Your Community

SUPPLEMENTAL AIR PURIFIERS IN CLASSROOMS CENTRALLY INSTALLED – FILTER CHECKS

HEPA AND CARBON FILTERS ARE REGULARLY CHECKED.



Please refer to the manufacturer's manual for details:

AeroMaxPRO III-Product Manual AeroMaxPRO IV-Product Manual



Note: Supplemental air purifiers feature a front display that is not considered to be accurate. It uses a sensor for air quality which is **not calibrated and not an indication of filter replacement.**

To request an operational check, please contact your local facilities group: UTSG F&S at 416-978-3000, UTM FMP at 416-864-8025, UTSc Facilities Management at 416-287-7579.

If there are further concerns regarding an air purifier unit in a specific location, please contact EHS (<u>ehs.office@utoronto.ca</u>).



The University of Toronto is closely monitoring the COVID-19 situation. Please visit our website, **utoronto.ca**, to read the latest updates.