



Operations Division Occupational Health and Safety

OHS Case ID: 04253LFQP069

Field Visit no: 04253LFQP070

Visit Date: 2017-MAR-13

Field Visit Type: INITIAL

Workplace Identification: UNIVERSITY OF TORONTO: MEDICAL SCIENCE BLDG 1 KING'S COLLEGE CIRCLE, TORONTO, ON, CANADA M5S 1A8

Notice ID:

Telephone: (416) 978-2028

JHSC Status: Active

Work Force #: 800

Completed %:

Persons Contacted: DAVID CAHALIN, JLL PM; HEATHER TAYLOR, DIRECTOR & JHSC MANAGEMENT REP; RICHARD HEGELE, VICE-DEAN; YANG TING SHEK, OHS SPECIALIST; ARTUR JAKUBOWSKI, JHSC WORKER REP; DOUG COLBY, COORDINATOR HAZ CONSTRUCTION, IRFAN MIRAJ, MANAGER HAZ CONST.

Visit Purpose: TO OBSERVE COMPLIANCE WITH THE OCCUPATIONAL HEALTH AND SAFETY ACT

Visit Location: MEETING ROOM 3169, ROOM 6334, ROOM 6318, ROOM 5334, ROOM 4334

Visit Summary: SEE NARRATIVE BELOW

Detailed Narrative:

Today's visit to this workplace by the Ministry of Labour (MOL) was to gather information following an occurrence. This inspector was accompanied by David Winter, MOL Hygiene Consultant.

The following items were observed/discussed:

The background of the occurrence was discussed.

Two Type 3 abatement projects were conducted between November 23, 2016 and were completed around January 6, 2017.

A third-party consultant was retained to monitor the abatement projects. A copy of the consultant's daily inspection report and air sampling reports have been requested.

An additional third party consultant was retained to review the areas of concern. Copies of air sampling and bulk/air sampling reports have been requested. Air sampling results are reported by OHS to be posted on the portal.

The workplace parties advised that occupants of the building are notified of the construction projects via list serve. Meetings were held in November with occupants. A copy of this notification has been requested.

The Asbestos Management Program is available on the U of T website.

Workparties advised that the mechanical shaft of concern has been sealed. The shaft was observed to be sealed in room 4334 and 6334. The mechanical shaft doors had not been sealed in room 5334 at the time of this visit. Workparties indicated that they would be sealed.

Table with 3 columns: Recipient, Inspector Data, Worker Representative. Includes names, titles, and signatures of Yang Ting Shek, Kristine Ewing, and Artur Jakubowski.

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at http://www.olrb.gov.on.ca/english/homepage.htm for more information.

Operations Division Occupational Health and Safety

Field Visit Report

OHS Case ID: 04253LFQP069

Field Visit no: 04253LFQP070

Visit Date: 2017-MAR-13

Field Visit Type: INITIAL

Workplace Identification: UNIVERSITY OF TORONTO: MEDICAL SCIENCE BLDG

Notice ID:

1 KING'S COLLEGE CIRCLE, TORONTO, ON, CANADA M5S 1A8

The was no dust observed in areas adjacent to the shaft door in room 6334 at the time of this visit.

~~The JHSC is aware of projects ongoing.~~ (K2)

The following documents have been requested:

Consultant's daily inspection reports and air sampling reports related to the asbestos abatement projects undertaken on the 3rd and 7th floor.

Air sampling and bulk sampling reports associated with room 6334.

Any notification issued to occupants regarding these construction projects.

Revised SOP for working in mechanical shafts.

The following documents were received:

Designated Substances in Building Materials Survey Report, MCB Laboratory Renovation P005-16-114, Medical Sciences Building (Building #005) - 1 King's College Circle dated December 9, 2016

Air Monitoring Report - February 25, 2017, University of Toronto-Medical Sciences Building, 1 King's College Circle, Toronto, Ontario, dated February 27, 2017, Safetech

Air Monitoring Report - March 1, 2017, University of Toronto-Medical Sciences Building, 1 King's College Circle, Toronto, Ontario, dated March 1, 2017, Safetech

Pinchin Ltd Asbestos Laboratory Certificate of Analysis, February 27, 2017, Dust from Lab Bench

Email to JHSC management representative, subject Room 6334, dated March 2, 2017

You are required under the OHS Act to post a copy of this report in a conspicuous place and provide a copy to the JHSC.

GENERAL INFORMATION:

Recipient	Inspector Data	Worker Representative
Name _____	KRISTINE EWING OCCUPATIONAL HEALTH & SAFETY INSPECTOR PROVINCIAL OFFENCES OFFICER 1600-5001 Yonge St, North York ON M7A 0A3 MOLCOMPLIANCEIHSTORW@ontario.ca Tel: (416) 270-1680 Fax: (647) 777-5013	Name _____
Title _____		Title _____
Signature _____	Signature 	Signature 

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.oltb.gov.on.ca/english/homepage.htm> for more information.



Operations Division Occupational Health and Safety

OHS Case ID: 04253LFQP069

Field Visit no: 04253LFQP070

Visit Date: 2017-MAR-13

Field Visit Type: INITIAL

Workplace Identification: UNIVERSITY OF TORONTO: MEDICAL SCIENCE BLDG
1 KING'S COLLEGE CIRCLE, TORONTO, ON, CANADA M5S 1A8

Notice ID:

For further information on Health and Safety the Ministry of Labour has a website at www.labour.gov.on. This website contains general information and guides, legislation and regulations, health and safety guidelines, engineering data sheets and hazard alerts.

To contact the Ministry of Labour to report a fatality, critical injury or concern: 1-877-202-0008

Recipient	Inspector Data	Worker Representative
Name _____	KRISTINE EWING OCCUPATIONAL HEALTH & SAFETY INSPECTOR PROVINCIAL OFFENCES OFFICER 1600-5001 Yonge St, North York ON M7A 0A3 MOLCOMPLIANCEIHSTORW@ontario.ca	Name _____
Title _____	Tel: (416) 270-1680 Fax: (647) 777-5013	Title _____
Signature <i>[Handwritten]</i>	Signature <i>[Handwritten]</i>	Signature <i>[Handwritten]</i>

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.olrb.gov.on.ca/english/homepage.htm> for more information.

